SFB BR 900-08

Project Application Form

Building Renewal Grant Application

Initial Submission Date:

Resubmittal Date:

Please provide as much of the requested information as possible. SFB staff will assist in developing required information that is not currently available.

District Name: Ft Thomas Unified District

Superintendent: Dr. Leon Ben

Contact Person: Derrick Bryce

Contact Phone Number:

Contact Email: dbryce@ftthomas.k12.az.us

School Site: Fort Thomas Elementary School

Buildings: 9999 School Wide

Description of Problem

Please include a detailed description of the issues, as well as a description of and a copy of any professional studies, citations or reports from government entities, recommended solutions, and any cost information or estimates. If additional space is needed, please attach.

The roof requires immediate attention and replacement. A visual inspection carried out by the Maintenance Director and a construction management firm has shown multiple sections (|10) where the roof membrane is bubbling and separating from the underlaying membranes and/or insulation layer. In November of 2011 a section of roof approximately 20x10 feet was replaced with insurance funds due to a breach and major leak in this section. The roof contractor performing the repair recommended the entire roof be replaced. It is estimated 80% of the elementary school roof area (or 36,340 square feet) will require repair or replacement. The Fort Thomas High School replaced 20,111 square feet of roof in 2011 at a cost of \$22.30 per square foot. We anticipate similar pricing for the replacement work at the elementary school.

Project Category: Roofing

Available Funding

Available Funding Source	Amount
Current unencumbered building renewal fund balance (Fund 690):	\$0.00
Amount of Local funds planned for this project	\$0.00

Please outline any associated insurance coverage.

9/10/2012 2:59:51 PM 1

Building Renewal Grant Application

The insurance agency covered the cost of the roof repair in 2011 since the breach in the roof required immediate attention in order to prevent water from intruding behind the walls and causing mold issues. At that time they informed the District that they would not cover the larger repair that is needed. The District is actively pursuing funding opportunities to address this deficiency as well as others.

Liaison:	Breuer	gbreuer@azsfb.gov	602-542-6139	
		Superintendent Printed Name		
		Superintendent Signature	Date	

9/10/2012 2:59:51 PM 2